

BIA 2 – Rural Safety and Regional Access Project
Potato Creek Bridge Photos

The following photos show the existing Bureau of Indian Affairs Potato Creek bridge. The bridge was constructed approximately 75 years ago, is narrow, creates a low sag vertical curve with steep road grades on both sides which decreases sight distance to the west. This project would determine if the bridge could be replaced with a concrete box culvert and the road profile raised to increase sight distance and flatten the vertical curves.



BIA 2 – looking west



BIA 2 – looking east – steep grade

BIA 2 – Rural Safety and Regional Access Project
Potato Creek Bridge Photos



BIA 2 – looking west – inadequate sight distance



Potato Creek Bridge - Profile

BIA 2 – Rural Safety and Regional Access Project
Potato Creek Bridge Photos

The following photos show the deterioration of the existing Bureau of Indian Affairs Potato Creek bridge.



Potato Creek Bridge – Under Deck



Potato Creek Bridge – Exposed Steel Reinforcement in Column

BIA 2 – Rural Safety and Regional Access Project
Potato Creek Bridge Photos



Potato Creek Bridge – Exposed Steel Reinforcement in Column



Potato Creek Bridge – Column Cracking and Spalling